

**Panasonic/Rasonic Panasonic and Rasonic Split Type Air Conditioner /
“Smaller” Series Split Type Air Conditioner / Window Split Type Air
Conditioner Standard Installation Service Fee**

A) <u>Split Type Air Conditioner / “Smaller” Series Split Type Air Conditioner Standard Installation Service Fee</u>	
<u>HP</u>	<u>Standard Installation Service Fee (HK\$)</u>
3/4 HP - 1 HP	\$ 1,800 per unit
1.5 HP	\$ 2,000 per unit
2 HP	\$ 2,200 per unit
2.5 HP	\$ 2,400 per unit
3 HP	\$ 3,100 per unit
B) <u>Window Split Type Air Conditioner Standard Installation Service Fee</u>	
<u>HP</u>	<u>Standard Installation Service Fee (HK\$)</u>
3/4 HP - 1 HP	\$ 1,500 per unit
1.5 HP - 2 HP	\$ 1,700 per unit
<u>Scope of the Split Type Air Conditioner Standard Installation Service:</u>	
1) Include refrigerant pipe, PVC drain pipe, pipe insulator, control wire between indoor and outdoor unit (16 ft. long for each and surface pipe). 2) Include refrigerant filling. 3) Include drill one hole on window glass (3 inch x 4 inch) 4) Connect the supplied power supply cable to the power supply/socket. (Customer needs to provide suitable power supply/socket.)	
<u>(Remarks ¹: For the split type air conditioner installation service, an on-site sighting service must be arranged in advance. The sighting fee is HK\$150 / visit.)</u>	
<u>Additional Installation Work Charges</u>	<u>Additional Charges (HK\$)</u>
Extra refrigerant pipe with refrigerant, pipe insulator and control wire (surface pipe)	\$ 70 (per ft.)
Extra drain pipe with pipe insulator (surface pipe)	\$ 25 (per ft.)
To dismantle the existing old split type air conditioner (1 x 1) / (1 x 2) / (1 x 3)	\$550/\$650/\$750 (per set)
Disposal the old split type air conditioner	FREE
Drill a hole (within 3 inch diameter) on inner wall and mend by cement (The wall thickness : 4 inch / 8 inch)	\$ 180/\$250 (per hole)

Remarks:

1. For the split type air conditioner installation service, an on-site sighting service must be arranged in advance. The sighting fee is HK\$150 / visit. The sighting fee will be charged even though the installation area is not suitable or customer do not employ our company to install the new split type air conditioner after the sighting service. Our company will provide the official quotation after the sighting service. The customer needs to confirm the quotation and complete the installation service within 30 days after the quotation issued. After the completion of the installation service, the paid sighting fee HK\$150 will be refunded from the installation service fee.
2. The Split Type Air Conditioner Standard Installation Service is only applicable on newly purchased and not installed Panasonic or Rasonic split type air conditioner
3. This price list is for reference purpose only. Price will be quoted separately under special circumstances. All the additional works and charges are subject to our quotation after the sighting service.
4. Other additional works not included on the above price list will be separately quoted. (Eg. Submission of Certificate of Completion of Minor Works MW05, scaffolding fee).
5. The installation location of air conditioner is decided by the customer, who is obligated to obtain the permit from co-owner of property, owner's corporations management office, building management company, HK Housing Authority, etc. on the right to use the common part comply with the obligations of the Building Deed of mutual covenant. The customer should confirm the installation details with our installation technician before work. If there is any dispute on the installation location and need to change the location after the installation works starts, additional dismantle and re-installation fee will be charged to the customer.
6. 12-month warranty is provided for the installation work (Start from the installation complete date). The warranty includes (i) Air conditioner aluminum frame (newly installed); (ii) Silicone to seal the glass. The warranty does not include: scaffolding and safety racks, which must be provided by the customer; Problems caused by poor maintenance (such as water leakage due to insufficient regular maintenance of the air-conditioner)
7. Split Type Air Conditioner Standard Installation Service does not cover reinstallation, dismantling, transportation or setup of any accessories/exterior equipment of the product.
8. The power supply/ socket provided by the customer must comply the Code of Practice for Electricity (Wiring) Regulations.
9. Additional Installation work must arrange and complete with the standard installation work. Otherwise, an additional surcharge will be applied.
10. The customer need to present the Product Warranty Card together with the official purchase invoice issued by the dealers of Hong Kong or Macau to our technician for verification.
11. Any blockage should be cleared by the customer before work. A removal fee will be charged in case additional labour is required to move the appliance to a serviceable area.

12. If the installation position is unsuitable or the air conditioner is unable to install due to technical or safety issue, our company reserves the right to refuse to provide the installation service.
13. Installation Service is only applicable to Shun Hing group authorized Hong Kong Official goods.
14. In the event of any dispute, our Company reserves the right to make the final decision.